



G3PO & BEGi

Kits Include:

- All chassis parts
- All rotor head parts
- Blades, ready for weight installation, blade weight and covering
- All pushrods, connectors, hardware, wheels
- 25 page photo illustrated manual with building and flying instructions.



You have to supply:

- Glue (foam safe CA mostly),
- Receiver, two pico servos, one nano or micro rudder servo
- Brushless motor, speed control, prop
- Appropriate battery.

Nothing else needed.

Recommended power:

1) Outrunner (best choice) Himax 2812-850,
APC 10x4.7 or 11x4.7 SF prop,
Phoenix 10 ESC, Any 10C to 12C, 1050 to 1320 3S1P LiPoly Battery.

2) Geared setup ~4100 KV long can motor like Himaxx 2025-4200 or similar, 6.6:1 geared, 11x4.7 or 12x6 APC SF.
Same battery/ESC as the outrunner

A brushed setup is discouraged as the Gyrocopter takes a lot of power to fly well.

\$150 includes shipping in the USA.

www.paypal.com to mnowell129@earthlink.net

Email for shipping outside USA. (mnowell129@earthlink.net)